


Service Manual

Blu-ray Disc Recorder

Model No. **DMR-PWT500GL**
DMR-PWT500GZ



Vol. 1

Colour:

(K).....Black Type

Notes: This model's BD Drive is VXY2119


When replacing HDD, Main P.C.B. or EEPROM
"HDD Error" indication is displayed and HDD must be
formatted.


After that, programme in the HDD will be lost.
In detail, please refer to each content in this service
manual.

15 Parts and Exploded Views


15.1. Exploded View and Mechanical Replacement Parts List

15.1.1. Casing Parts & Mechanism Section





15.1.2. Exploded View OF BD drive (Mechanism Section)



15.1.3. Packing & Accessories Section

