



MSZ-AP22VGKD MSZ-AP25VGKD MSZ-AP35VGKD
MSZ-AP42VGKD MSZ-AP50VGKD
1-13. INDOOR UNIT STRUCTURAL PARTS




1-14. ACCESSORY AND REMOTE CONTROLLER




MSZ-AP22VGKD MSZ-AP25VGKD MSZ-AP35VGKD
MSZ-AP42VGKD MSZ-AP50VGKD

1-15. INDOOR UNIT ELECTRICAL PARTS AND FUNCTIONAL PARTS



1-16. INDOOR UNIT HEAT EXCHANGER



2-1. ELECTROSTATIC ANTI-ALLERGY ENZYME FILTER

Every 3 months:

- Remove dirt by a vacuum cleaner.
- Put it back to its original position, and install all tabs of the air filter.

When dirt cannot be removed by vacuum cleaning:


- Soak the filter and its frame in lukewarm water before rinsing it.
- After washing with water, dry it well in shade. Install all tabs of the air filter.

Every year:


- Replace it with a new air cleaning filter for best performance.

Model		Part No.
MSZ-AP22VGD	MSZ-AP22VGKD	MAC-2320FT
MSZ-AP25VGD	MSZ-AP25VGKD	
MSZ-AP35VGD	MSZ-AP35VGKD	
MSZ-AP42VGD	MSZ-AP42VGKD	
MSZ-AP50VGD	MSZ-AP50VGKD	
MSZ-AP25VGD2	MSZ-AP25VGKD2	
MSZ-AP35VGD2	MSZ-AP35VGKD2	
MSZ-AP42VGD2	MSZ-AP42VGKD2	
MSZ-AP50VGD2	MSZ-AP50VGKD2	MAC-2310FT-E
MSZ-AP60VGD	MSZ-AP60VGKD	
MSZ-AP71VGD	MSZ-AP71VGKD	
MSZ-AP80VGD	MSZ-AP80VGKD	
MSZ-AP60VGD2	MSZ-AP60VGKD2	
MSZ-AP71VGD2	MSZ-AP71VGKD2	
MSZ-AP80VGD2	MSZ-AP80VGKD2	

MSZ-AP22/25/35/42/50VGD, VGKD MSZ-AP25/35/42/50VGD2, VGKD2



MSZ-AP60/71/80VGD, VGKD MSZ-AP60/71/80VGD2, VGKD2



MITSUBISHI ELECTRIC CORPORATION

HEAD OFFICE: TOKYO BUILDING, 2-7-3, MARUNOUCHI, CHIYODA-KU, TOKYO 100-8310, JAPAN

© Copyright 2019 MITSUBISHI ELECTRIC CORPORATION

Issued: Jul. 2024. No. OBB824 REVISED EDITION-E

Issued: Aug. 2023. No. OBB824 REVISED EDITION-D

Issued: Jan. 2023. No. OBB824 REVISED EDITION-C

Issued: Oct. 2021. No. OBB824 REVISED EDITION-B

Issued: Feb. 2021. No. OBB824 REVISED EDITION-A

Published: Mar. 2019. No. OBB824

Made in Japan

Specifications are subject to change without notice.